


N85BA
LOE #3

JORDAN PROPELLER



SERVICE

SAN ANTONIO - HOUSTON

Propeller Logbook

JORDAN PROPELLER SERVICE INC.

103 EAST RHAPSODY SAN ANTONIO, TEXAS 78216
Certificated Repair Station No. EK2R797K

PROPELLER S/N 681429 HAS BEEN REPAIRED

IAW MANUALS 720415 & SPM 100-1.

DISASSEMBLED, VISUALLY INSPECTED, REFINISHED

BLADES, REASSEMBLED w/ NEW SEALS AND RECOND

CYLINDER. STATICALLY BALANCED.

PERTINENT DETAILS ON FILE UNDER W.O. 9008

SIGNED [Signature] DATE 6-11-03

MECHANIC MAKING INSTALLATION ON A/C MUST C/W FAR 43.9

PROPELLER MAINTENANCE RECORD

LEFT ENGINE

Hub Model 2A36C23-P-CE6

Blade Design S-84B-O

Diameter _____

Hub Ser. No. 681429

Blade Ser. Nos.

No. 1 C 64180 YS

No. 2 C 64012 YS

No. 3 _____

No. 4 _____

No. 5 _____

PITCH RANGE

High _____ Low _____

Feather _____ Reverse _____

Governor Model _____

RIGHT ENGINE

Hub Model _____

Blade Design _____

Diameter _____

Hub Ser. No. _____

Blade Ser. Nos.

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____

PITCH RANGE

High _____ Low _____

Feather _____ Reverse _____

Governor Model _____

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK
6-13-03	3129.2	Removed/Reinstalled THIS PROPELLER
	TACH & TT	3/4 68/429 FOR INSP/REPAIR BY
		JORDAN PROPELLER. Ref. W/O 3604
	904.9	
	T30 (4-90)	
		ADVANTAGE AIRCRAFT SERVICES, INC. FAA CRS Q2AR598N 355 PINSON DRIVE, CORPUS CHRISTI, TX 78406
7-2-04	3197.8 TACH & TT	913.5 T30 (4-90) Completed an
		Annual INSP using Beech form P/N 98-32227J.
		Ref. W/O 3958
		ADVANTAGE AIRCRAFT SERVICES, INC. FAA CRS Q2AR598N 355 PINSON DRIVE, CORPUS CHRISTI, TX 78406

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK
8-1-05	3289.5	TACH & TOTAL 1065.2 T30 (4-90) Completed
		an Annual insp. using 35 mm Section 7. Profiled
		PAINTED BLADES W/O 4314
		ADVANTAGE AIRCRAFT SERVICES, INC. FAA CRS Q2AR598N 355 PINSON DRIVE, CORPUS CHRISTI, TX 78406
9-1-06	3339.0	TACH & TOTAL 1124.3 T30 (4-90)
		Completed an Annual INSP. using 35 m.m. Section 7.
		W/ AD 98-25-13 NO DYC NOTED. AD 05-14-11 N/A
		W/O 4671
		ADVANTAGE AIRCRAFT SERVICES, INC. FAA CRS Q2AR598N 355 PINSON DRIVE, CORPUS CHRISTI, TX 78406
10-17-07	3411.2 TACH & TT	1196.5 T30 (4-90) Completed
		An Annual INSP using 35 mm Section 7 Profiled
		BLADES W/ AD 98-25-13 NO DYC NOTED. AD 06-24-07
		N/A NO Rework BY CSE. W/O 34995
		ADVANTAGE AIRCRAFT SERVICES, INC. FAA CRS Q2AR598N 355 PINSON DRIVE, CORPUS CHRISTI, TX 78406

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK
12/1/08	3459.6	TACH & TT 1244.9 T30 (4/90) Profiled Blades C/W AD 98-25-13. No dye noted Completed an Annual insp. W/05283 DSD-JRP
		ADVANTAGE AIRCRAFT SERVICES, INC. FAA CRS Q2AR598N 355 PINSON DRIVE, CORPUS CHRISTI, TX 78408
2-8-10	3512.4	TACH & TOTAL 1297.7 T30 (4/90) Completed an Annual Insp using 35 shop manual Chapter 5 C/W AD 98-25-13 NO dye noted. Profiled & Painted Blades W/05571 DSD-JRP
		ADVANTAGE AIRCRAFT SERVICES, INC. FAA CRS Q2AR598N 355 PINSON DRIVE, CORPUS CHRISTI, TX 78408

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK
4-27-11	3556.7	TACH & TT 1342.0 T50 (4/90) Completed an Annual insp using 35 shop manual C/W AD 98-25-13, no Red dye noted Ret W/05832 DSD-JRP
		ADVANTAGE AIRCRAFT SERVICES, INC. FAA CRS Q2AR598N 355 PINSON DRIVE, CORPUS CHRISTI, TX 78408
4-1-2013	3582.5	Removed/Reinstalled this Propeller for Reseal/Refinish by Jordan Propeller W/015811 installed Per McCavley INSTRUCTION W/ NEW HARDWARE W/06322 DSD-JRP
		ADVANTAGE AIRCRAFT SERVICES, INC. FAA CRS Q2AR598N 355 PINSON DRIVE, CORPUS CHRISTI, TX 78408

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS



PROPELLER LOG BOOK ENTRY

Propeller: N85BA McCauley 2A36C23-P-CEG S/N 681429 Date: 7/24/2014
Prop Total Time: 3592.0 TSO: 1377.3 (4/90) Indicated Time: 3692.0 TACH W/O: 6784
COMPLETED AN ANNUAL INSPECTION USING BEECH FORM P/N 98-38999M.
PROFIED BLADES. C/W AD 98-25-13 NO DYE LEAKAGE NOTED. RESEARCHED AD'S THRU 2014-14
ISSUE.
549 Pinson Drive
Corpus Christi, TX 78406
(361) 289-1884

ADVANTAGE AIRCRAFT SERVICES, INC.
FAA CRS Q2AR598N
549 PINSON DRIVE, CORPUS CHRISTI, TX 78406

David D. Holzschuh
FAA CRS Q2AR598N



PROPELLER LOG BOOK ENTRY

Propeller: N85BA McCauley 2A36C23-P-CEG S/N 681429 Date: 5/1/2016
Prop Total Time: 3602.3 TSO: 1387.6 (4/90) Indicated Time: 3602.3 TACH W/O: 7242
COMPLETED AN ANNUAL INSPECTION USING 35 SERIES SHOP MANUAL SECTION 7
PROFIED BLADES. C/W AD 98-25-13 NO DYE LEAKAGE NOTED. RESEARCHED AD'S THRU 2016-07
ISSUE.
549 Pinson Drive
Corpus Christi, TX 78406
(361) 289-1884

ADVANTAGE AIRCRAFT SERVICES, INC.
FAA CRS Q2AR598N
549 PINSON DRIVE, CORPUS CHRISTI, TX 78406

David D. Holzschuh
FAA CRS Q2AR598N



ALAMO AERO SERVICES, INC.

P.O. BOX 460212 SAN ANTONIO TX 78246 PHONE (210) 525-9677 FAX (210) 525-1226

DATE: 4/23/2018
TACH: 3617.8
TSO: 1403.1

REG.NO: N85BA
PROP S/N: 681429

Performed the following maintenance:

- Performed annual inspection in accordance with Beech Bonanza Series Maintenance Manual.

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. The maintenance and / or inspection performed on the prop identified above was performed in accordance with current federal aviation regulations and was found to be airworthy for return to service.

Mike Kappel
IA# 3325060



ALAMO AERO SERVICES, INC.

P.O. BOX 460212 SAN ANTONIO TX 78246 PHONE (210) 525-9677 FAX (210) 525-1226

DATE: 5/8/2019
TACH: 3659.2
TSO: 1444.5

REG.NO: N85BA
PROP S/N: 681429

Performed the following maintenance:

- Performed annual inspection in accordance with Beech Bonanza Series Maintenance Manual.

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. The maintenance and / or inspection performed on the prop identified above was performed in accordance with current federal aviation regulations and was found to be airworthy for return to service.

Mike Kappel
IA# 3325060



P.O. BOX 460212 SAN ANTONIO TX 78246 PHONE (210) 525-9677 FAX (210) 525-1226

DATE: 8/7/2020

TACH: 3706.1

TSO: 1491.4

REG.NO: N85BA

PROP S/N: 681429

Performed the following maintenance:

- Performed annual inspection in accordance with Beech Bonanza Series Maintenance Manual.
- Complied with AD 98-25-13 by inspection of propeller for leakage. No defects noted.
- Removed propeller governor p/n: C210452 K/N, s/n: 860303 for repair and reinstalled after repair.

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. The maintenance and / or inspection performed on the prcp identified above was performed in accordance with current federal aviation regulations and was found to be airworthy for return to service.

Mike Kappel
IA# 3325060

N85BA, Date: 9/4/2021/2021, Tach: 3766.9

Airframe: Beech V35A, SN: D-8820, ACTT: 3766.9


Engine: Continental IO-520-B, S/N: 234768-R, TTE: 1219.8, OH date 2/28/1995.

Propeller: McCauley 2A36C23-P-CEG, S/N: 681429, TT: 3766.9, TSMOH 1552.2.

Complied with annual inspection per FAR43 app. D. Performed post inspection engine run and operational check.

ADs checked through this date. See AD Listing dated 9/4/2021.

No ADs due this date.

I certify that this **PROPELLER** has been inspected in accordance with an **ANNUAL** inspection and has been determined to be in airworthy condition. Christopher C. Comer AP4342669IA. 

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS
& MINOR ADJUSTMENTS**

[illegible]